

GENERAL PURPOSE COMMITTEE

SECTION 2 INFRASTRUCTURE

GENERAL PURPOSE COMMITTEE - INFRASTRUCTURE

Table of Contents

Meeting Date: 25 June 1996

Page 2

ITEM	SUBJECT	PAGE
-	SECTION 2 - INFRASTRUCTURE.	
23:	TENDERS FOR PLANT HIRE GT020/323 PT01/ENG	3
24:	MACQUARIE STREET ROAD CLOSURE 1341/R PT03/ENG	4

***** END OF TABLE OF CONTENTS *****

ITEM: 23 TENDERS FOR PLANT HIRE**FILE NUMBER:** GT020/323 PT01/ENG

REPORT:

Tenders for the hire of plant on a comprehensive basis for the period 1st July, 1996 to 30th June, 1997, closed at 2pm on 31st May, 1996.

A total of fifty nine tenders were received for the supply of various items of plant. Tenders have been listed in order of price within respective plant categories.

The selection of plant from the Schedule list is based on availability, price and performance.

The current tender period expires on 30 June 1996 and as such will be necessary to adopt the plant schedule at this General Purpose Committee Meeting to enable the commencement of the new schedule from 1 July 1996.

A copy of the Schedule is available for perusal by interested Councillors.

RECOMMENDATION:

That the schedule list for the hire of plant on a comprehensive basis for the period 1 July 1996 to 30 June 1997.

ATTACHMENTS:

There are no supporting documents for this report.

FN:IN625NBX.E01

****** END OF ITEM 23 ******

ITEM: 24 MACQUARIE STREET ROAD CLOSURE**FILE NUMBER:** 1341/R PT03/ENG

REPORT:

At its last meeting Council resolved that this matter be deferred until the next General Purpose Committee.

Concern has been expressed by the Police regarding the safety of a short section of road on the eastern side of Macquarie Street running from Macquarie Street to Ham Street.

While there is a "give way" sign controlling the intersection of the road with Macquarie Street, there is concern regarding the speed of south bound vehicles exiting Macquarie Street via this section of road, particularly in view of the operation of an adjacent pre-school with its associated traffic generation of carers dropping off and picking up children. The intersection itself is also considered unsatisfactory due to angle at which the side street intersects with Macquarie Street. A plan will be displayed at the meeting.

A relatively simple solution would be to close the side street at its intersection with Macquarie Street with access to properties on this section of road being gained via Ham Street, thus eliminating the point of potential conflict and providing a safer environment in this area.

RECOMMENDATION:

That procedures be undertaken to close the section of road between Macquarie Street and Ham Street, South Windsor, at its intersection with Macquarie Street.

ATTACHMENTS:

There are no supporting documents for this report.

FN:IN625NBX.E02

****** END OF ITEM 24 ******